

June 24, 2015

MANAGEMENT | TRAINING | LAB SERVICES www.NVLLABS.com

Shimon Mizrahi Rainier Commons LLC 918 S. Horton Street, Suite 1018 Seattle, WA 98134

Subject: Polychlorinated Biphenyl (PCB) Substrate Sampling

IPWP1 Close Out

Rainier Commons, LLC

Site Address: 3100 Airport Way S, Seattle, WA

NVL Project#: 2012-494

Dear Mr. Mizrahi:

Rainier Commons, LLC retained NVL Laboratories to conduct the sampling at their Old Rainier Brewery site located at 3100 Airport Way South, Seattle, Washington and this letter has been prepared to convey the results.

This report compiles the results of the PCB bulk material samples collected from the concrete and sandstone substrate materials on buildings 10, 11, and 13 pursuant to Condition 8 of the EPA's Risk Based Work Plan Approval for Rainier Commons.

All samples were collected pursuant to NVL's Substrate Sampling Plan (Exhibit 8 to Phase I IPWP) and all sampling protocols and procedures referenced therein.

NVL Labs conducted sampling pursuant to IPWP1 close out on five separate dates between December 1<sup>st</sup>, 2014, and January 30<sup>th</sup>, 2015, at the request of Rainier Commons LLC. Samples were collected from the concrete and sandstone substrate materials on the buildings to test for the presence of residual PCB's following work to remove PCB-containing paint coatings from the building.

Initial samples were collected prior to final clearance and approval of all work areas and prior to all "punchlist" work being performed. While these samples are not valid clearance samples the results are reported here as early, pre-clearance sample results, for information purposes only.

Sample results are compared against the substrate screening limit of 1ppm.

Phone: 206 547.0100 | Fax: 206 634.1936 | Toll Free: 1.888.NVL.LABS (685.5227) 4708 Aurora Avenue North | Seattle, WA 98103-6516



The below tables present the results of the substrate sampling.

	Pre-Clearance Sampling								
Sampling Date	Sample Number	Sampling Location	Substrate Type	Sample Results (PPM)					
8/4/14	8414MK-1	Building 13 West Elevation	Concrete	2.5					
8/4/14	8414MK-2	Building 13 West Elevation	Concrete	2.5					
8/4/14	8414MK-3	Building 13 South Elevation	Concrete	1.3					
8/4/14	8414MK-4	Building 13 East Elevation	Concrete	ND					
9/29/14	Bldg- 11West	Building 11 West Elevation	Concrete	2.9					
9/29/14	Bldg- 13North	Building 13 North Elevation	Concrete	ND					
10/9/14	10914-BULK-2	Building 10 West Elevation	Sandstone	4.3					

ND = Non-Detect

PPM = Parts per million or milligrams per kilogram (mg/kg)

	Post-Clearance Compliance Sampling								
Sampling Date	Sample Number	Sampling Location	Substrate Type	Sample Results (PPM)					
12/1/14	12114-PCB-1	Bldg 11 West Elevation	Sandstone	1.1					
12/1/14	12114-PCB-2	Building 13 North Elevation	Concrete	ND					
1/30/15	13015-MG-N	Building 13 North Elevation	Concrete	<1					
1/30/15	13015-MG-S	Building 13 South Elevation	Concrete	< 0.99					
1/30/15	13015-MG-E	Building 13 East Elevation	Concrete	< 0.97					
1/30/15	13015-MG-W	Building 13 West Elevation	Concrete	1.6					

ND = Non-Detect

PPM = Parts per million or milligrams per kilogram (mg/kg)

Prepared By

Marcus Gladden **NVL** Laboratories

Industrial Hygienist

Reviewed By

Munaf Khan Project Manager

Laboratory Director / President

Attachments:

Laboratory Testing Reports, NVL Labs Batch No.

1501799

1421389

1418022

1417235

1413963

Substrate Sampling Rainier Commons, LLC Project No. 2012-494 June 24<sup>th</sup>, 2015



February 3, 2015

Mr. Munaf Khan

NVL Field Services Division 4708 Aurora Ave. N. Seattle, 98103

Re: NVL Batch 1501799.00

Project Name/Number: 2012-494

Project location: 3100 Airport Way South Seattle, WA 98134

Dear Mr. Khan,

Enclosed please find test results for samples submitted to our laboratory for analysis. Preparation and analysis of these samples were conducted in accordance with published industry standards and methods specified on the attached analytical report.

The content of this package consists of the following:

- -Case Narrative & Definition of Data Qualifiers
- -Analytical Test Results
- -Applicable QC Summary
- -Client Chain-of-Custody (CoC)
- -NVL Receiving Record

This report package contains a total of 11 pages of analytical test results along with customer COC and other related documents.

The report is considered highly confidential and will not be released without your approval. Samples are archived for two weeks following analysis. Samples that are not retrieved by the client will be discarded after two weeks.

Thank you for using our laboratory services. If you need further assistance, please contact us at 206-547-0100 or 1-888-NVLLABS.

Sincerely,

Nick Ly, Technical Director

Enclosure: Sample Results



#### **Case Narrative:**

The following summarizes samples received on date as shown on the accompanied Chain of custody by NVL Laboratories, Inc. from NVL Field Services Division for Project No. 2012-494. Samples were logged in for PCB analysis per client request using both customer sample ID's and laboratory assigned ID's as listed on the Chain-of-Custody (CoC). All samples as received were processed and analyzed within specified turnaround time without any abnormalities and deviations that may affect the analytical results. All quality control requirements were acceptable unless stated otherwise. The conditions of all samples were acceptable at time of receipt and all samples submitted with this batch were analyzed unless stated otherwise on the CoC.

Test Results are reported based on milligram per kilogram (mg/kg) for PCB samples as shown on the analytical reports.



#### **Definition Appendix**

#### Terms

% Rec Percent recovery. Below Reporting Limit(RL) or Limit of Quantitation(LoQ) of the < instrument. Blank contamination. The recorded results is associated with a В contaminated blank. DF **Dilution Factor** J The reported concentration is an estimated value because something may be present in the sample that interfered with the analysis. J1 The reported concentration is an estimated value because the laboratory control sample (LCS) is out of control limits. J2 The reported concentration is an estimated value because the percent recovery for matrix spike is out of control limits. J3 The reported concentration is an estimated value because the relative percent difference(RPD) for duplicate analysis is out of control limits. J4 Percent recovery is outside of established control limits. LCS Laboratory Control Sample. Limits The upper and lower control limits for spike recoveries. LOQ Limit of quantitation( same as RL) mg/kg Milligrams per kilogram. ND Analyte not detected or below the reporting limit of the instrument or methodology PPM Parts per Million. QC Batch Group Quality Control Batch Group. The entity that links analytical results and supporting quality control results.



#### **Definition Appendix**

**Terms** 

R The data are not reliable due to possible contamination or loss of

material during preparation or analysis. Re-sampling and reanalysis

are necessary for verification.

RL Reporting Limit. The minimum concentration that can be quantified

under routine operating conditions.

RPD Relative Percent Difference. The relative difference between

duplicate results( matrix spike, blank spike, or samples duplicate)

expressed as a percentage.

RPD Limit The maximum RPD allowed for a set of duplicate

measurements(see RPD).

SMI Surrogate has matrix interference.

Spike Conc. The measured concentration, in sample basis units, of a spiked

sample.

SURR-ND Surrogate was not detected due to matrix interference or dilution.

ug/m3 Micrograms per cubic meter.

ug/mL Micrograms per milliliter

mg/Kg milligram per kilogram

# ORGANICS LABORATORY SERVICES



Proj	Address ect Manager Phone	4708 Aurora Ave Seattle, WA 9810 Mr. Marcus Glad (206) 547-0100 (b) (6)	. N. 03 den	NVL Batch Number 150179 TAT 5 Days Rush TAT Due Date 2/6/2015 Time Email marcus.g@nvllabs.com Fax (206) 634-1936	<b>AH</b> No 1:45 PM	
Pro	ject Name/N	lumber: 2012-49	4 Project Lo	cation: 3100 Airport Way S. Seattle	e, WA 98134	
Subo	category Qu	antitative analysis				
Ite	m Code OR	G-05	8082 PCB Aroclors <bul< td=""><td>k&gt;</td><td></td><td></td></bul<>	k>		
Тс	otal Numb	er of Samples	S comment of the state of the s		Rush Samples	
	Lab ID	Sample ID	Description			A/R
1	15010069	13015-MG-N				Α
2	15010070	13015-MG-S				А
3	15010071	13015-MG-E				Α
4	15010072	13015-MG-W				A

Y-11-11-11-11-11-11-11-11-11-11-11-11-11	Print Name	Signature	Company	Date	Time
Sampled by	Client				
Relinquished by	Client				
Office Use Only	Print Name	Signature	Company	Date	Time
Received by	Fatima Khan		NVL	1/30/15	1345
Analyzed by	Evolyn Ahula	Starle	NVL	7/2/15	14:58
Results Called by		11.5 = 3.5 30.011.4 245.231111	i i	, ,	
Faxed Emailed					
Special Instructions:					

Entered By: Fatima Khan

Date: 1/30/2015

Time: 2:39 PM

1 of 1

Page 5 of 11

4708 Aurora Ave North, Seatile, WA 98103 p 206,547.0100 f 206.634.1936 www.nvllabs.com

# **ANALYSIS REPORT**

# NVIL.

# **Polychlorinated Biphenyls by Gas Chromatography**

Client SDG Number Date Reported Project Number Location	NVL Field Services Division 1501799.00 02/03/2015 2012-494 3100 Airport Way South Seattle, WA 98134	Samples Received* Analyzed By Samples Analyzed* Analysis Method Preparation Method	4 Evelyn Ahulu 4 8082A 3546PR (PCB) * for this test only
Sample Number	er 13015-MG-N	Received	01/30/2015
Lab Sample ID	15010069	Matrix	Material
Initial Sample Siz	ze 2.0083 gm	Units of Result	mg/Kg, as received
Analyte		RL	Final Result Analysis Date
Aroclor-1016		1.0	< 1.0 02/02/2015
Aroclor-1221		1.0	< 1.0 02/02/2015
Aroclor-1232		1.0	< 1.0 02/02/2015
Aroclor-1242		1.0	< 1.0 02/02/2015
Aroclor-1248		1.0	< 1.0 02/02/2015
Aroclor-1254		1.0	< 1.0 02/02/2015
Aroclor-1260		1.0	< 1.0 02/02/2015
PCBs, Total		1.0	<1
Comments: Building 13	3 North Concrete		
Sample Number	er 13015-MG-S	Received	01/30/2015
Lab Sample ID	15010070	Matrix	Material
Initial Sample Siz	ze 2.0194 gm	Units of Result	mg/Kg, as received
Analyte		RL	Final Result Analysis Date
Aroclor-1016		0.99	< 0.99 02/02/2015
Aroclor-1221		0.99	< 0.99 02/02/2015
Aroclor-1232		0.99	< 0.99 02/02/2015
Aroclor-1242		0.99	< 0.99 02/02/2015
Aroclor-1248		0.99	< 0.99 02/02/2015
Aroclor-1254		0.99	< 0.99 02/02/2015
Aroclor-1260		0.99	< 0.99 02/02/2015

Phone: 206.547.0100 | Fax: 206.634.1936 | Toll Free: 1.888.NVL.LABS (685.5227) 4708 Aurora Avenue North | Seattle, WA 98103

0.99

PCBs, Total

Comments: Building 13 South Concrete

< 0.99

# **ANALYSIS REPORT**



# **Polychlorinated Biphenyls by Gas Chromatography**

Sample Number	13015-MG-E	Received	01/30/2015
Lab Sample ID	15010071	Matrix	Material
Initial Sample Size	2.0587 gm	Units of Result	mg/Kg, as received
Analyte		RL	Final Result Analysis Date
Aroclor-1016		0.97	< 0.97 02/02/2015
Aroclor-1221		0.97	< 0.97 02/02/2015
Aroclor-1232		0.97	< 0.97 02/02/2015
Aroclor-1242		0.97	< 0.97 02/02/2015
Aroclor-1248		0.97	< 0.97 02/02/2015
Aroclor-1254		0.97	< 0.97 02/02/2015
Aroclor-1260		0.97	< 0.97 02/02/2015
PCBs, Total Comments: Building 13 East	Concrete	0.97	<0.97
Sample Number	13015-MG-W	Received	01/30/2015
Lab Sample ID	15010072	Matrix	Material
Initial Sample Size	2.0293 gm	Units of Result	mg/Kg, as received
Analyte		RL	Final Result Analysis Date
Aroclor-1016		0.99	< 0.99 02/02/2015
Aroclor-1221		0.99	< 0.99 02/02/2015
Aroclor-1232		0.99	< 0.99 02/02/2015
Aroclor-1242		0.99	< 0.99 02/02/2015
Aroclor-1248		0.99	< 0.99 02/02/2015
Aroclor-1254		0.99	1.6 02/02/2015
Aroclor-1260		0.99	< 0.99 02/02/2015
PCBs, Total		0.99	1.6

Comments: Building 13 West Concrete

Phone: 206.547.0100 | Fax: 206.634.1936 | Toll Free: 1.888.NVL.LABS (685.5227) 4708 Aurora Avenue North | Seattle, WA 98103



Phone: 206 547-0100 Fax: 206 634-1936

### **Quality Control Results**

Project Number:	2012-494			SDG Nı Project	ımber: Manager:		501799 Iunaf Kha	n		
QC Batch(es):	Q251			Analysi	s Method:	808	2A			
QC Batch Method: Preparation Date:	3546PR (PCB) 02/02/2015			Analysis De	scription:		ychlorinat omatogra		henyls by Ga	as
Blank: MB-1501799										
Analyte	Blank Result	Units	DF		RL		Control Limit			Qualifiers
Aroclor-1016	ND	mg/Kg	1		1.0		1			Qualifiers
Aroclor-1010	ND ND	mg/Kg	1		1.0		1			
Aroclor-1232	ND ND	mg/Kg	1		1.0		1			
Aroclor-1242	ND ND	mg/Kg	1		1.0		1			
Aroclor-1248	ND ND	mg/Kg	1		1.0		1			
Aroclor-1254	ND ND	mg/Kg	1		1.0		1			
Aroclor-1260	ND ND	mg/Kg	1		1.0		1			
PCBs, Total	ND ND	mg/Kg	1		1.0		1			
Surrogates:	ND	9,9				% Rec				
Tetrachloro-m-xylene			1			83	40-140			
Decachlorobiphenyl			1			97	40-140			
Lab Control Sample	: MSPK-1501799									
	Blank Spike			Spike			% Rec			
Analyte	Result	Units	DF	Conc.		% Rec	Limits			Qualifiers
Aroclor-1254 Surrogates:	20.1	mg/Kg	1	20.0		101	40-140			
Tetrachloro-m-xylene			1			77	40-140			
Decachlorobiphenyl			1			103	40-140			
Lab Control Sample	: LCS-1501799									
Lab Control Sample	Duplicate: LCS Du	ıp-150179	9							
	Blank Spike			Spike						
Analyte	Result	Units	DF	Conc.		% Rec	Limits	RPD	RPD Limit	Qualifiers
Aroclor-1016	14.2	mg/Kg	1	20.0		71	40-140			
	12.5			20.0		63	40-140	13	50	
Aroclor-1260	16.5 18.2	mg/Kg	1	20.0		83	40-140	40	50	
Surrogates:	18.2			20.0		91	40-140	10	50	
Tetrachloro-m-xylene			1			81	40-140			
1 Guadillolo-III-Aylelle			'			83	40-140			
Decachlorobiphenyl			1			104	40-140			
. 1 - 7						87	40-140			

#### Surrogate Recovery Summary Report

Client NVL Field Services Division	<u>on</u>	SDG Number	<u>1501799</u>	
<b>Project</b> <u>2012-494</u>				
Customer Sample ID	Lab Sample ID	Analyte	Recovery	Limits
13015-MG-N	15010069	Decachlorobiphenyl	98%	40-140
13015-MG-N	15010069	Tetrachloro-m-xylene	68%	40-140
13015-MG-S	15010070	Decachlorobiphenyl	95%	40-140
13015-MG-S	15010070	Tetrachloro-m-xylene	72%	40-140
13015-MG-E	15010071	Decachlorobiphenyl	96%	40-140
13015-MG-E	15010071	Tetrachloro-m-xylene	87%	40-140
13015-MG-W	15010072	Decachlorobiphenyl	96%	40-140
13015-MG-W	15010072	Tetrachloro-m-xylene	86%	40-140
LCS Dup-1501799	LCS Dup-1501799	Decachlorobiphenyl	87%	40-140
LCS Dup-1501799	LCS Dup-1501799	Tetrachloro-m-xylene	83%	40-140
LCS-1501799	LCS-1501799	Decachlorobiphenyl	104%	40-140
LCS-1501799	LCS-1501799	Tetrachloro-m-xylene	81%	40-140
MB-1501799	MB-1501799	Decachlorobiphenyl	97%	40-140
MB-1501799	MB-1501799	Tetrachloro-m-xylene	83%	40-140
MSPK-1501799	MSPK-1501799	Decachlorobiphenyl	103%	40-140
MSPK-1501799	MSPK-1501799	Tetrachloro-m-xylene	77%	40-140

<sup>\*</sup> Recovery outside limits

#### INITIAL AND CONTINUING CALIBRATION VERIFICATION

SDG No: <u>1501799</u> Contract: <u>N/A</u>

Determination: 8082 PCB Aroclors < Material>

Run	Sample	Source	Analyzed	Analyte	True	Found	Unit	% Rec	Limits
R000244	CCV1 1016 -1260	PCB_2014-1-17	02/02/2015	Aroclor-1016	5	5	ug/mL	100	80-120
		PCB_2014-1-17	02/02/2015	Aroclor-1260	5	5	ug/mL	100	80-120
	CCV1 1254	PCB_2014-1-18	02/02/2015	Aroclor-1254	5	5	ug/mL	100	80-120
	ICV 1016-1260	PCB_2014-2-4	02/02/2015	Aroclor-1016	5	4.94	ug/mL	99	85-115
		PCB_2014-2-4	02/02/2015	Aroclor-1260	5	5.614	ug/mL	112	85-115
	CCV2 1016 - 1260	PCB_2014-1-17	02/02/2015	Aroclor-1016	5	4.743	ug/mL	95	80-120
		PCB_2014-1-17	02/02/2015	Aroclor-1260	5	4.695	ug/mL	94	80-120
	CCV2-1254	PCB_2014-1-18	02/02/2015	Aroclor-1254	5	4.959	ug/mL	99	80-120

<sup>%</sup> Rec = Percent recovery

<sup>\* =</sup> Percent recovery not within control limits

### NVL Laboratories, Inc. 4708 Aurora Ave N, Seattle, WA 98103

# CHAIN of CUSTODY SAMPLE LOG

1501799

p 206.547.0100 | f 206.634.1936 | www.nvllabs.com NVL Batch Number Client NVL Laboratories Inc Client Job Number 2012-494 Street 4708 Aurora Ave N **Total Samples** Seattle, WA 98103 ☐ 1 Hr ☐ 6 Hrs ☐ 3 Days ☐ 2 Hrs ☐ 1 Day ☐ 4 Days ☐ 4 Hrs ☐ 2 Days ☐ 5 Days ☐ 3 Days ☐ 10 Days ☐ 4 Days Turn Around Time Project Manager Munaf Khan Project Location 3100 Airport Way South Seattle, WA 98134 Please call for TAT less than 24 Hrs Email address Phone: (206) 447-0263 Fax: (206) 447-0299 Asbestos Air 🔲 PCM (NIOSH 7400) 🔲 TEM (NIOSH 7402) 🔲 TEM (AHERA) 🔲 TEM (EPA Level II) 🔲 Other ☐ Asbestos Bulk ☐ PLM (EPA/600/R-93/116) ☐ PLM (EPA Point Count) ☐ PLM (EPA Gravimetry) ☐ TEM BULK ☐ Mold/Fungus ☐ Mold Air ☐ Mold Bulk Rotometer Calibration Other Metals **RCRA Metals** □ All 8 **METALS** Det. Limit Matrix ☐ All 3 ☐ Arsenic (As)
☐ Barium (Ba) Air Filter Soil Chromium (Cr ☐ Total Metals FAA (ppm) Copper (Cu) Drinking water Paint Chips in % ☐ TCLP Lead (Pb) ICP (ppm) Nickel (Ni) ☐ Dust/wipe (Area) ☐ Paint Chips in cm ☐ Cadmium (Cd) ☐ Mercury (Hg) ☐ Cr 6 GFAA (ppb) Zinc (Zn) X Other (Specify) PCB'S ✓ Other Types Fiberglass Nuisance Dust of Analysis Silica Respirable Dust Condition of Package: 
Good Damaged (no spillage) Severe damage (spillage) A/R Seq. # Client Sample Number Comments 13015-MG- N 1 RULLOING 13 Nonth CONCULTE 13 2 13015 - MG -S SUUTA CONCLUTE BULLOING 3 E BULLOING 4 BULLDING WEST 5 6 7 8 9 10 11 12 13 14 15 Company Date Time 11.00 1-30-15 NV Sampled by Relinquished by Received by Analyzed by Results Called by Results Faxed by Special Instructions: Unless requested in writing, all samples will be disposed of two (2) weeks after analysis. Results report to

# **ANALYSIS REPORT**



# **Polychlorinated Biphenyls by Gas Chromatography**

Client SDG Number Date Reported Project Number Location	NVL Field Services Division 1421389.00 12/08/2014 2012-494 3100 Airport Way South, Seattle, WA 98134	Samples Received* Analyzed By Samples Analyzed* Analysis Method Preparation Method	2 Evelyn Ahulu 2 8082A 3546PR (PCB) * for this test only
Sample Numbe	er 12114-PCB-1	Received	12/01/2014
Lab Sample ID	14145438	Matrix	Material
Initial Sample Siz	e 2.0219 gm	Units of Result	mg/Kg, as received
Analyte		RL	Final Result Analysis Date
Aroclor-1016		0.99	< 0.99 12/04/2014
Aroclor-1221		0.99	< 0.99 12/04/2014
Aroclor-1232		0.99	< 0.99 12/04/2014
Aroclor-1242		0.99	< 0.99 12/04/2014
Aroclor-1248		0.99	< 0.99 12/04/2014
Aroclor-1254		0.99	1.1 12/04/2014
Aroclor-1260		0.99	< 0.99 12/04/2014
PCBs, Total Comments: Bldg. 11 W.	. Sandstone	0.99	1.1
Sample Numbe	er 12114-PCB-2	Received	12/01/2014
Lab Sample ID	14145439	Matrix	Material
Initial Sample Siz	e 2.0009 gm	Units of Result	mg/Kg, as received
Analyte		RL	Final Result Analysis Date
Aroclor-1016		1.0	< 1.0 12/04/2014
Aroclor-1221		1.0	< 1.0 12/04/2014
Aroclor-1232		1.0	< 1.0 12/04/2014
Aroclor-1242		1.0	< 1.0 12/04/2014
Aroclor-1248		1.0	< 1.0 12/04/2014
Aroclor-1254		1.0	< 1.0 12/04/2014
Aroclor-1260		1.0	< 1.0 12/04/2014
PCBs, Total		1.0	<1

Phone: 206.547.0100 | Fax: 206.634.1936 | Toll Free: 1.888.NVL.LABS (685.5227) 4708 Aurora Avenue North | Seattle, WA 98103

Comments: Bldg. 13 N. Concrete

# **NVL Laboratories, Inc.** 4708 Aurora Ave N, Seattle, WA 98103

# CHAIN of CUSTODY SAMPLE LOG

1	4	2	1	3	8	9
---	---	---	---	---	---	---

,	- Colonia	
	1	}
		TV.
		S

206.547,01	100   f2	06.634.1936	www.nvllabs.cor	n						72 10	00	
	Client	VL Labo	ratories Inc					Number		-		
	_		ora Ave N			Clie		Number 20				
			VA 98103			-	Total	Samples 4	<u>'</u>			
oiect M:	_	/lunaf Kh				Turn		nd Time 1	Hr 🔲 6 Hr		ys 🗌 10	Days
oject I o	cation 3	100 Airp	ort Way South			_		2	Hrs	ay 🗍 4 Da		
oject Lo	S	Seattle, V	VA 98134							Il for TAT less		-lre
	.=					-	Email	address	i icase cai	1701 1741 1030	) (IIII) Z-1	
Г	Phone: (	206) 447	'-0263 Fax:	(206) 44	7-0299							
Asbe	stos Air	PCM	(NIOSH 7400)	☐ TEM (I	VIOSH 740	2) 🗌 TE	M (AH	IERA) 🗌 TE	EM (EPA Le	vel II) 🔲 (	Other	
Asbe	stos Bul	k 🗌 PLM	(EPA/600/R-93/	116) 🗌 F	LM (EPA F	oint Cou	nt)	PLM (EPA C	Gravimetry)	□ ТЕМ В	ULK	
Mold	/Fungus	Mold	l Air 🔲 Mold Bu	lk 🔲 F	Rotometer	Calibrati	on					
METALS Total TCLP Cr 6	Metals r Types	☐ ICP ☐ GFA	(ppm) Air Fi (ppm) Drink (ppb) Dust/	ing water wipe (Area nce Dust	a) 🗌 Pain		%	CRA Metals   Arsenic (As)   Barium (Ba)   Cadmium (C	Lead	omium (Cr	Other Maria All 3 Coppe Nickel Zinc (2	er (Cu) (Ni)
	nalysis	Silica		able Dust								
onditio	n of Pac	kage: 🗌	Good Dama	ged (no s	oillage) 🔲	Severe o	amage	e (spillage)				
Seq. #	Lab ID		Client Sample									A/R
1			12114-PCB	m	BLOG	11 W	. SA	NOSTUNE				
2			12114 - PCB	- 2	BLOG	13 N	,	CONLINET	۲			
3												
4												
5	_											
6												
7												
8												
9												
10												
11												
12												
13												
14						-						
15												
		Print I	Bolow	Sian Bel	nu	7 -		Company		Date	Tim	A
	Sampled	. A		1	~_			NVL	UBS	12/1/		دت:
	quished		4		1 4			9		61	16:	$\infty$
	Received	111	Mrs Vaidly	V	1 5	11	/	N.	1	12/1	14/15	d)
	nalyzed		0001801	1				100		· CV	fe ( to	
Dogulte	s called	БУ										
Result	s Faxed	hu		1				1			1	

# **NVL Laboratories, Inc.** 4708 Aurora Ave N, Seattle, WA 98103

Analysis Report
Polychlorinated Biphenyls (PCBs)

p 206.547.0100 | f 206.634.1936 | www.nvllabs.com



Client: NVL Field Services Division

Address: 4708 Aurora Ave. N.

Attention: Mr. Marcus Gladden

Seattle, WA 98103

Project Location: 3100 Airport Way South Seattle, WA 98134

NVL Batch #: 1418022.00

Method No.: EPA 8082

Client Project #: 2012-494

Date Received: 10/9/2014

Matrix: Bulk

Samples Received: 2

Samples Analyzed: 2

Lab Sample ID:	14128826	14128827
Client Sample ID:	10914-BULK-1	10914-BULK-2
Sample Description:	Blue Paint, Bldg. 13 SW	Sandstone, Bldg. 10 W
Sample Weight (g)	1.0403	2.0156
PCB Type	mg/Kg(ppm)	mg/Kg(ppm)
Aroclor 1016	ND	ND
Aroclor 1221	ND	ND
Aroclor 1232	ND	ND
Aroclor 1242	ND	ND
Aroclor 1248	ND	ND
Aroclor 1254	100.00	2.8
Aroclor 1260	29.00	1.5
Total: PCB Concentration	129.0	4.3
Reporting Limit (RL)	19.0	1.0

**Remarks:** mg/Kg = Milligrams per kilogram

ppm = Parts per million by weight

ND = None Detected (less than RL)

<RL = Below the reporting limit of instrument

Sampled by: Client

Analyzed by: Shalini Patel
Reviewed by: Nick Ly

Date: 10/10/2014 Date: 10/10/2014

Nick Ly, Technical Director

Preparation and analysis of these samples were conducted in accordance with published test methods. Unless stated otherwise, the condition of all samples was acceptable at time of receipt. Reported sample results are based on dry weight and method QC results are acceptable unless stated otherwise. If samples were not collected by NVL personnel, then the accuracy of the results is limited by the methodology and acuity of the sample collector. This report shall not be reproduced except in full, without written approval of NVL Laboratories, Inc.. Responsibility for interpretation of the reported data rests with the client.

### **NVL Laboratories, Inc.** 4708 Aurora Ave N, Seattle, WA 98103

# CHAIN of CUSTODY SAMPLE LOG

1418022



p 206.547.0 <b>1</b> 0	00   f206	.634,1936	www.nv	llabs.com							· • ·	_
,	Client N'	√l Labo	ratories I	nc			NVL Batch					
			ra Ave N				Client Job	Number				
,	_		A 98103				Total	Samples	2_			
roject Ma	-						Turn Aroun	d Time	1 Hr 🔲	3 Hrs		□ 10
roject Loc	nation 3	00 Airp	ort Way S	South					]2 Hrs 🔀 ]4 Hrs 🗍	1 և 2 հ	☐ 4 ☐ 5	
oject Loc			'A 98134								 ΓAT less tha	an 24 Hrs
	_						- Email	address				
Р	Phone: (2	06) 447	-0263	Fax: (2	:06) 44	7-0299						
Asbes	stos Air	□ РСМ	(NIOSH 7	7400)	] TEM (	NIOSH 740	2) TEM (A	HERA)	TEM (EP	'A Level	II) 🗌 C	Other
Asbes	stos Bulk	☐ PLM	(EPA/600	/R-93/116	6) 🔲 I	PLM (EPA P	oint Count)	PLM (E	PA Gravime	etry)	_ ТЕМ В	ULK
☐ Mold/i	Fungus	☐ Mold	Air 🗌 N	lold Bulk	□F	otometer C	alibration					
METALS Total N TCLP Cr 6 Other of Ana	Metals Types	Det. Lin FAA CONTROL FAA FIBER FIBER Silica	(ppm) (ppm) A (ppb)	Tatrix Air Filte Drinking Dust/wip Nuisance Respirat	g water pe (Area e Dust	a) ☐ Paint	Chips in %		As) 🔲 Ba) 🗍	Chromiu Lead (P Mercury	um (C D	ther Metals ] All 3 Copper (C Nickel (Ni) Zinc (Zn)
Condition			Good [	] Damage			Severe damag	e (spillage	e)			
Seq.#	Lab ID		Client 9	Sample N	lumher	Comments						A
1	Labib			BULK -		BLUE P		6 13	SW			
2			10114	L.	2	SANDSTO		5 10				
3				47		JANUSCO	NE   DEU	6 10	~	_		
4												
5												
6												
7												
8												
9												
10												
11												
12												
13											-	
14												
15												
		Print E			Sian Bel	ow		Compan	4		Date	Time
S	ampled b	y Man	us 6	Linday	_/			NVL	LABS		10/9/1	4 11:3
Reling	quished b	У	. 7	-\	1	1			17		1	14'.15
Re	eceived b	N/10	on K	N	0		m		W		MAI	19 14
Ar	nalyzed b	у										1
Results	Called b	у						ļ				
Results	s Faxed b	у										
Special	Instruc	lione: II	nless recu	lested in	writing	all samples	will be disposed	t of two (2	) weeks aft	er analv	sis.	
1 -	report to	uons. U	ness requ	iosiou III i	many,	an odmpies	so disposed	. 0, 1, 0 (2	,o an	i analy	<del>_</del> .	

# Analysis Report Polychlorinated Biphenyls (PCBs)

4708 Aurora Ave N, Seattle, WA 98103 p 206.547.0100 | f 206.634.1936 | www.nvllabs.com



Client: NVL Field Services Division

Address: 4708 Aurora Ave. N.

Attention: Mr. Munaf Khan

Seattle, WA 98103

Project Location: 3100 Airport Way South. Seattle, WA 98134

**NVL Batch No. 1417235** 

Method No.: EPA 8082

Client Project #: 2012-494

Date Received: 9/29/2014

Matrix: Bulk

Samples Received: 2

Samples Analyzed: 2

			Samples Analyzed: 2
Lab Sample ID:	14125190	14125191	
Client Sample ID:	Bldg-11 West	Bldg-13 North	
Sample Description:	West Wall Concrete	North Wall Concrete	
Sample Weight (g)	2.2160	2.0110	
PCB Type	mg/Kg(ppm)	mg/Kg(ppm)	
Aroclor 1016	ND	ND	
Aroclor 1221	ND	ND	
Aroclor 1232	ND	ND	
Aroclor 1242	ND	ND	
Aroclor 1248	ND	ND	
Aroclor 1254	1.9	ND	
Aroclor 1260	1	ND	
	7.		
Total: PCB Concentration	2.9	ND	
Reporting Limit (RL)	0.9	1.0	

Remarks: mg/Kg = Milligrams per kilograms

ppm = Parts per million by weight

ND = None Detected (less than RL)

<RL = Below the reporting limit of instrument

Sampled by: Client

Analyzed by: Evelyn Ahulu

Reviewed by: Nick Ly

Date:10/01/2014

Date:10/02/2014

Nick Ly, Technical Director

Preparation and analysis of these samples were conducted in accordance with published test methods. Unless stated otherwise, the condition of all samples was acceptable at time of receipt. Reported sample results are based on dry weight and method QC results are acceptable unless stated otherwise. If samples were not collected by NVL personnel, then the accuracy of the results is limited by the methodology and acuity of the sample collector. This report shall not be reproduced except in full, without written approval of NVL Laboratories, Inc.. Responsibility for interpretation of the reported data rests with the client.

4708 Aurora Ave N, Seattle, WA 98103 Tel: 206.547.0100 Emerg. Cell: 206.914.4646 1.888.NVL.LABS (685.5227) www.nvllabs.com

# CHAIN of CUSTODY SAMPLE LOG

1417235

		, ,									
	Client	NVL Labo	ratories	s Inc				tch Number		_	
	Street	4708 Auro	ra Ave	N			Client	Job Number 20			
		Seattle, W	/A 9810	)3				otal Samples	21		
Project M	anager	Munaf Kha	an				Turn A	Around Time	1 Hr	<b>X</b> 3 [	] 10
roiect Lo	cation	3100 Airpo	ort Way	South			_	_	] 2 Hrs	☐ 4 <b>~</b>	
•		Seattle, W	/A 9813	34					_	TAT less than 2	4 Hrs
							Er	nail address			
	Phone:	(206) 447			: (206) 44				-		
Asbe	estos A	ir DCM	(NIOSH	17400)	ТЕМ	(NIOSH 74	02) TEN	/ (AHERA)	TEM (EPA Leve		
Asbe	estos B	ulk 🗌 PLM	(EPA/6	00/R-93	/116) 🗌	PLM (EPA	Point Count)	PLM (EPA	. Gravimetry)	TEM BULK	
☐ Mold	l/Fungu	ıs 🗌 Mold	Air 🗌	Mold B	ulk 📗	Rotometer	Calibration				
METALS Total TCLF Cr 6	Metals	☐ ICP	(ppm) (ppm) A (ppb)	☐ Dus	Filter king water t/wipe (Are	ea) 🗌 Pa	int Chips in % int Chips in c	RCRA Metals Aluminum (A) Arsenic (As) Barium (Ba)	AL) Berylliu ) Bismutt ) Boron (	ım (Be h (Bi) (B) ☐ Nicl	Metals I 3 oper (Cu) kel (Ni) c (Zn)
of Ar	r Type: nalysis	Silica	<u> </u>	Resr	ance Dust	st		Dedunion	Balk	:00	
Conditio	on of Pa	ackage: 🗌	Good	∐ Dam	aged (no s	spillage) [	Severe da	mage (spillage)			
Seq. #	Lab	1D	Clien	t Samp	le Numbe	Commer	nts				A/R
1			Blde	3 1	1 west	•	ve of u	und co	nevite		
2			Bld	ν 1 —	13 nox	h	north !	any co	noste		
3				0		,					
4											
5											
6											
7											
8											
9											
10											
11											
12											
13											
14											
15											
		Print I	Selow		Sian Be	low		Company		Date	Time
	Sample		W.I.	Jan	be	a Cons	Diason	DVL	spe	9.19.14	
	nquishe	V 1	Revi	Cha	MV	In Is	Den		1	9.29,14	111582
	Receive	1.0	time	Hon	(II	thon the		nu	il kalo	Glecy ly	1515h
		ed by Evo	Jun F	Hand	7	Ch	Anh	N	VLlaber	10/1/14	15:00
	ts Calle			10.00	70						
	ts Faxe										
								15.			
		~ ~			in writing	, all sample	s will be disp	osed of two (2) v	veeks after analy	ysis.	
Results	s report	to ( 🔨	UNA	F							
1											

#### **NVL Laboratories, Inc.** 4708 Aurora Ave N, Seattle, WA 98103

**Analysis Report Polychlorinated Biphenyls (PCBs)** 

p 206.547.0100 | f 206.634.1936 | www.nvllabs.com

NVL Batch No. 1413963.00 Client: NVL Field Services Division

Address: 4708 Aurora Ave. N.

Seattle, WA 98103

Project Location: 3100 Airport Way South Seattle, WA 98134

Attention: Mr. Munaf Khan

Client Project #: 2012-494 Date Received: 8/12/2014

Method No.: EPA 8082

Matrix: Bulk

Samples Received: 4 Samples Analyzed: 4

Lab Sample ID:	14108005	14108006	14108007	14108008
Client Sample ID:	8414MK-1	8414MK-2	8414MK-3	8414MK-4
Sample Description:	West side 1	West side 1A	South side	East side
Sample Weight (g)	2.0523	2.0463	2.0108	2.0073
PCB Type	mg/Kg(ppm)	mg/Kg(ppm)	mg/Kg(ppm)	mg/Kg(ppm)
Aroclor 1016	ND	ND	ND	ND
Aroclor 1221	ND	ND	ND	ND
Aroclor 1232	ND	ND	ND	ND
Aroclor 1242	ND	ND	ND	ND
Aroclor 1248	ND	ND	ND	ND
Aroclor 1254	1.5	2.5	1.3	ND
Aroclor 1260	1	ND	ND	ND
Total: PCB Concentration	2.5	2.5	1.3	ND
Reporting Limit (RL)	1.0	1.0	1.0	1.0

Remarks: mg/Kg = Milligrams per kilograms

ppm = Parts per million by weight

ND = None Detected (less than RL)

<RL = Below the reporting limit of instrument

Sampled by: Client

Analyzed by: Evelyn Ahulu Reviewed by: Nick Ly

Date:08/18/2014 Date:08/18/2014

Nick Ly, Technical Director

Preparation of these samples were conducted in accordance with EPA Method 3546 or other published test methods as noted in this report. Unless stated otherwise, the condition of all samples was acceptable at time of receipt. Reported sample results are based on dry weight and method QC results are acceptable unless stated otherwise. If samples were not collected by NVL personnel, then the accuracy of the results is limited by the methodology and acuity of the sample collector. This report shall not be reproduced except in full, without written approval of NVL Laboratories, Inc.. Responsibility for interpretation of the reported data rests with the client.

4708 Aurora Ave N, Seattle, WA 98103 Tel: 206.547.0100 Emerg. Cell: 206.914.4646 1.888.NVL.LABS (685.5227) www.nvllabs.com

# CHAIN of CUSTODY SAMPLE LOG



	Client	NVL Labo	ratorie	s Inc				<b>NVL</b> Ba	tch Number				
	Street	4708 Auro	ora Ave	N			-	Client .	Job Number	2012-494	4		
		Seattle, V	VA 981	03				To	tal Samples	4	-		
Proiect M	lanager	Munaf Kh	an					Turn A	round Time	☐ 1-Hr	8-Hrs	] 2	<b>3</b> 5
		3100 Airp		y Sout	h					2-Hrs 4-Hrs	12-Hrs [	3	<u> </u>
,		Seattle, V								TI PROPERTY OF STATE	24-Hrs [se call for TA	_ 4 Eless than	24 Hrs
								En	nail address	1000	0 0011101 171	r icos triai	241110
	Phone:	(206) 447	-0263	Fax	k: (206) 4	47-0	299						
Asbe	estos Aiı	PCM	(NIOSI	H 7400	TEM	1 (NIC	OSH 7402	) TEM	(AHERA)	TEM (E	PA Level II)	Oth	ner
☐ Asbe	estos Bu	Ik 🗌 PLM	(EPA/6	00/R-9	3/116)	PLM	(EPA Po	int Count)	☐ PLM (E	PA Gravim	etry)	TEM BUL	.K
☐ Mold	l/Fungus	Mold	Air 🗌	Mold E	Bulk 🗌	Roto	ometer Ca	alibration					
☐ TCLF	Metals	☐ ICP ☐ GFA	(ppm) (ppm) A (ppb)	Drin	Filter nking wate st/wipe (Ar	ea)	☐ Paint	Chips in % Chips in cr Specify)	Cadmiun	As)	All 8 Chromium Lead (Pb) Mercury (F	(C	er Metals All 3 opper (Cu) ickel (Ni) nc (Zn)
	nalysis	Fiber	T (		sance Dust pirable Du		A Utner (	Specify) _	455				
	7	kage:		Dan	naged (no	spilla	ge) 🗌 S	Severe dan	nage (spillage	e)			
Seq.#	Lab II	)	Clien	t Samn	le Numbe	r Co	mments						A/R
1	Lub II				<- 1	-	Control of the Contro	side	1				- AK
2			0	-( • ( )	2,		4	300	1 A				
3					3	1		to sid	,				
4					4	+-		st ste					
5						+	Cas	ST Sie	The contract of the contract o				
6						1							
7						+-							
8													
9						1							
10						1							
11						+							
12						+		-				House the sails	
13						+							
14						+-							
15			-			+							
15						1					FIRST	029	
		Print B		V.	Sian Be	low	0 M	$\sim$	Company			36 8 8	Time
	Sampled	1 1	Anat	-	1	-	201	agu.	NVL	CAR		414	
-	quished	-	1-ref		1	7	-	0	1 /	100	5	12/14	1700
	eceived		wen	t	m		NA		- 100	16	7/	12119	1700
	nalyzed				-								
	s Called				-								
Results	s Faxed	by										1	
		ctions: Ur		quested	l in writing,	, all sa	amples wi	ll be dispos	sed of two (2)	weeks after	er analysis.		